

# Island County Water Well Information



**WellKey: DCP**

## General Information

Owner Name (log): Dave Farmer

DOE Tag: ALT149 DOE NOI: [WE049](#)

Well Address: SR 525 (from parcel address)


Well Parcel: [R23028-217-1740](#)

Served Parcel:

Horiz/Vert Accuracy: Site Plan / DEM

Site Type: Well

DOE ID  
[453382](#)



SWI Rating: Low Risk

## Construction Information

Construction Date:

Driller Name: Dahlman Pump


LS Elevation: 299 ft. MSL

Depth Well:

TD Elevation: 196 ft. MSL

WL Measurements: [1 measurement \(Click to View\)](#)

WL Elevation: 279 ft. MSL



## Water Quality Information

Water Samples: [3 samples \(Click to View\)](#)


Average/Median/Maximum Arsenic: 0.002 / 0.002 / 0.002 mg/l

Average/Median/Maximum Chloride: 21.00 / 21 / 21 mg/l

Average/Median/Maximum Hardness: 116.00 / 116 / 116 mg/l

Average/Median/Maximum Nitrate: 2.52 / 2.24 / 3.84 mg/l

Bacteria Samples (distribution): [6 samples \(Click to View\)](#)



## Public Water System Information

Pws Name: Backwoods Water System

PwsID: [AD214](#)

Approved Connects: 8

Pws Source #: SO# 1

Pws Source Name: Well #1 ALT149

Note: Underlined items in **bright blue** are hyperlinks to additional information / resources.

Questions? Contact the [Island County Hydrogeologist](#), or visit the [Hydrogeology Web Page](#).

Report Generated: 12/31/2020